
Urban Ledgestone Building Stone

Typical Elevation • 20:50:30 Ashlar Bond • 3/8" Mortar Joints



Guidelines for Installation:

- 1. Two UL22 units load on top of each other will bond with one UL50.
- 2. A UL22/UL50 combination will bond with two UL35s.
- 3. UL35 units should form a staggered bonding line by crossing with UL22s.
- 4. Maintain a minimum 4" between vertical joints.
- 5. Maintain a maximum 5 7 foot horizontal joint length.
- 6. Maximum vertical joint is the height of the tallest unit.
- 7. To maintain the standard ratio of sizes in the wall, UL50 units should be placed approximately 1 - 1-1/2' apart. UL50 units should not touch each other.

Avoid:

- Stepping or stringing together more than 2 3 units of the same height.
- Creating box patterns in the wall.
- Stack bonding.

Size	Percent	Pieces/	Nominal Length
		sq.ft	of one Piece
UL22	20	11	31-3/4"
UL35	50	19	31-3/4"
UL50	30	8	32"

*One piece of Building Stone may be comprised of 2 or more pieces.




arriscraft.com | 800.265.8123

General Installation Guidelines

- Arriscraft recommends the use of a Portland cement-lime mortar, proportioned to a 1:1:6 ratio.
- Masonry units should be laid with full head and bed joints except where they are used for weep holes or ventilation.
- Bevel mortar from rear face to prevent protrusion into cavity.
- Prevent excessive mortar droppings by cutting off excess mortar with trowel as the units are laid.
- Butter head joints of unit being placed in wall.
- Place unit to tightly compress mortar.
- Do not re-adjust unit once it has been set in place.
- Tool joints when mortar is thumbprint hard. This timing will depend on the mortar properties and weather conditions.
- Tool joints to a tightly compressed surface to achieve the most weather resistance. Concave tooled joints provide the best resistance to moisture penetration.
- After tooling, any excess mortar and dust should be brushed from the masonry surface using a soft bristle brush. Avoid rubbing or pressing the mortar into the units.
- Refer to additional guidelines on the BASIC CARE sheet.

Joint Profile:



October 2016

arriscraft.com | 800.265.8123